

Garage Daniel Lessard



2509, route du Président-Kennedy
Notre-Dame-des-Pins
G0M1K0

1 855 202 5567



Vehicle

**Ford Explorer XLT 4WD 2.3L MAG 20" CUIR
ACCIDENTÉ**

Year	Odometer
2023	37776
Transmission	Traction
Automatic	Four wheel drive
Engine	Fuel
4 cylinders	
Serial number	Stock number
1FMSK8DH3PGA45531	36338
Color	Certified
Burgundy	



Equipment

Exterior doors : 4 doors, Transmission : Automatic, Car type : Suv, Cylinders : 4 cylinders, Motor : 2.3, Drivetrain : Four wheel drive, Wheels : Alloy, Air conditioning, Cruise control, Heated Driver Seat, Heated mirrors, Power locks, Power Mirrors, Power driver seat, Power steering, Power windows, Reverse park assist, Steering wheel controls, Adjustable steering wheel, Dual zone A/C, ABS Brakes, Rear defrost, Alarm system, Stability control, Traction control, Intermittent wipers, Rear spoiler, AM/FM stereo, MP3 Player, Bucket seats, Consumption highway (L/100 KM) : 8.7, Consumption city (L/100 KM) : 11.6, Torque : 310 @ 3500, Horsepower : 300 @ 5500, Reverse

Price

\$16,995

Taxes not included

Description

XLT 4WD, CUIR CHAUFFANT, VOLANT CHAUFFANT, ANGLE MORT, MAG 20 POUCES ACCIDENTÉ

Comments

THE VEHICLE IS RUNNING. A VGA (SALVAGE VEHICLE) INSPECTION WILL BE REQUIRED UPON COMPLETION OF THE REPAIRS. MECHANICAL COMPONENTS ARE OK. AIRBAGS AND SEAT BELTS ARE OK. ALL STRUCTURAL REPAIRS MUST BE PERFORMED IN ACCORDANCE WITH THE REPAIR STANDARDS AND REGULATIONS OF YOUR PROVINCE. REPAIRS REQUIRED: REPLACE THE REAR BODY PANEL (TRUNK REAR PANEL). REPLACE THE LEFT REAR TAIL LIGHT. REPAIR

Repairs

Warranty

WarrantyDescriptionText!

Legal warranty : D - None (LPC 37,38)

I acknowledge having received a copy of the label

Date _____ Signature _____



Sticker number : 2255706